



10/538785

~~cc/cj~~

PATENT
Customer Number 22,852
Attorney Docket No. 10189.0001-00

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re U.S. Patent No.: 7,301,357)
Inventors: Dai SHINOZAKI et al.)
Issue Date.: November 27, 2007)
For: INSPECTION METHOD AND)
INSPECTION EQUIPMENT)

Certificate

DEC 27 2007

U.S. PATENT & TRADEMARK OFFICE

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Sir:

REQUEST FOR CERTIFICATE OF CORRECTION

Pursuant to 35 U.S.C. § 255, and 37 C.F.R. § 1.323, this is a request for a Certificate of Correction in the above-identified patent. The mistake(s) identified in the appended Form are of a clerical or typographical nature, or of minor character, and resulted from an error made in good faith by patentee(s). The Commissioner is hereby authorized to charge the \$100 fee set forth in 37 C.F.R. § 1.20(a) to Deposit Account 06-0916.

Two (2) copies of PTO Form 1050 are appended. The complete Certificate of Correction involves one (1) page. Issuance of the Certificate of Correction containing the correction is earnestly requested.

12/21/2007 CNGUYEN2 00000017 060916 7301357
01 FC:1811 100.00 DA

DEC 28 2007

PATENT
Customer Number 22,852
Attorney Docket No. 10189.0001-00


Please charge any required fees not included herewith to Deposit Account

06-0916.

Respectfully submitted,

FINNEGAN, HENDERSON, FARABOW,
GARRETT & DUNNER, L.L.P.

Dated: December 19, 2007

By: 

Brad C. Rametta
Reg. No. 54,387
(404) 653,6552

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. 7,301,357

APPLICATION NO.: 10/538,785

ISSUE DATE: November 27, 2007

INVENTOR(S): Dai SHINOZAKI et al.

It is hereby certified that an error or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In claim 6, column 7, lines 19-22, "tester, circuit, the drivers being connected to the respective pairs of probe pins to apply the drivers applying a voltage, which causes a fritting phenomenon to the respective electrodes," should read --tester, the drivers applying a voltage, which causes a fritting phenomenon, to the respective electrodes,--.

MAILING ADDRESS OF SENDER

Finnegan, Henderson, Farabow,
Garrett & Dunner, L.L.P.
901 New York Avenue, N.W.
Washington, D.C. 20001-4413

DEC 28 2007

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. 7,301,357

APPLICATION NO.: 10/538,785

ISSUE DATE: November 27, 2007

INVENTOR(S): Dai SHINOZAKI et al.

It is hereby certified that an error or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In claim 6, column 7, lines 19-22, "tester, circuit, the drivers being connected to the respective pairs of probe pins to apply the drivers applying a voltage, which causes a fritting phenomenon to the respective electrodes," should read --tester, the drivers applying a voltage, which causes a fritting phenomenon, to the respective electrodes,--.

MAILING ADDRESS OF SENDER

Finnegan, Henderson, Farabow,
Garrett & Dunner, L.L.P.
901 New York Avenue, N.W.
Washington, D.C. 20001-4413

DEC 28 2007